




Allows you both to block/ stretch the wire quickly and to make the line cord.

Use: every beginning and end of the line with cable ø 1 mm. However, it is recommended every 30-50 meters at least.



Support for 1 and 2 mm wires. Use: 1 per meter or at inclination changings. They can be also glued.



Support for 1 and 2 mm wires. Use: To make angles from 90° to 170° - for angles bigger than 90° should be used 2 pieces.

